## Product name: Oxygen (Gases)

Supplier/ Manufacturer:

Takoradi Gas Ltd P.O.Box 1050 Takoradi, Ghana 0540 111 898

# Emergency phone: 0244 330 594.

054 011 1899 / 020 860 4051 tgl@tglgh.com

Section 2 : COMPOSITION/ INGREDIENT INFORMATION					
C.A.S.	CONCENTRATION %	Ingredient Name	OSHA PEL	ACGIH TLV	OSHA STEL
7782-44-7	Typically > 99.6 (MSDS also applies to 90 – 99.7%)	OXYGEN (+N2 & Ar)	NONE	NONE	NONE

Section 3 : HAZARD IDENTIFICATION		
Emergency Overview:	Oxygen gas is colorless, odorless, non-toxic cryogenic liquid or colorless, odorless, oxidizing gas. Liquid releases will quickly vaporize to gas.	
	The chief physical hazard associated with releases of the gas is its oxidizing power which can greatly accelerate the burning rate for both common and exotic combustible materials. Emergency personnel must practice extreme caution when approaching oxygen releases because of the potential for intense fire.	
	The primary health hazard at atmospheric pressure is respiratory system irritation after exposure to high oxygen concentrations. Maintain oxygen levels in air above 19.5% and below 23.5%. While up to 50% oxygen can be breathed for more than 24 hours without adverse effects, high concentrations in open air accelerate combustion and increase the risk of fire and explosion of combustible or flammable materials.	
Route of entry:	Inhalation, skin and eye contact.	
Effects of acute exposure		
-	No adverse effects expected.	
	No adverse effects expected.	
Inhalation:	May cause breathing difficulty. Prolonged exposure to high oxygen levels (>75%) can cause central nervous system depression: signs/symptoms can include headache, dizziness, drowsiness, poor coordination, slowed reaction time, slurred speech, giddiness and unconsciousness. May cause coughing and chest pain. May cause lung damage. May cause soreness of the throat.	
Ingestion:	Not a likely route of exposure.	
Effects of chronic exposure:	None known.	
Reproductive effects:	Oxygen deficiency during pregnancy has produced developmental abnormalities in humans and experimental animals.	
	Section 4 : FIRST AID MEASURES	
Skin contact:	None required.	
Eye contact:	None required.	
Inhalation:	RESCUERS SHOULD NOT ATTEMPT TO RETRIEVE VICTIMS OF EXPOSURE TO THIS PRODUCT WITHOUT ADEQUATE PERSONAL PROTECTIVE EQUIPMENT. At a minimum, Self-Contained Breathing Apparatus should be worn.	
	Remove victim(s) to fresh air, as quickly as possible. If not breathing qualified personnel should administer artificial respiration. Get medical attention. IKeep person warm and at rest.	
Ingestion:	No first aid should be needed. Not considered a potential route of exposure.	

repair the leak. Storage requirements: Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool, dry, well-ventilated, fireproof area, away from flammable materials and corrosive atmospheres. Store away from hea and ignition sources and out of direct sunlight. Do not store near elevators, corridors or loading docks. Do not allow area where cylinders are stored to exceed 52°C (125°F). Move cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not drop cylinders or permit them to strike each other. Secure cylinders firmly. Leave the valve protection cap in-place (where provided) until cylinder is placed into service and after it is taken out of service. Use designated CGA fittings and other support equipment. Do not use adapters. Do not heat cylinder by any means to increase the discharge rate of the product from the cylinder. Use chec valve or trap in discharge line to prevent hazardous backflow into the cylinder. Do not use oils o grease on gas-handling fittings or equipment.		Section 5 : FIRE FIGHTING MEASURES
Vigorously accelerates combustion. Extinguishing modia Use appropriate extinguishing media for surrounding fire. Special procedures Section criatines formating apparatus required. Friefighters should wear the usual protective gear. Cool fire applicable evacuated, if necessary, to upwind area. Remove containers from fire area if without risk. Auto-ignition temporature: Not applicable. Flash point (°C), method: Not applicable. Lower flammability limit (% vol): Not applicable. Explosion Data Sensitivity to mechanical impact Avoid impact against container. Explosion Data Sensitivity to mechanical impact Section 7: HANDLING AND STORAGE Lower gear. Wear glowes and googles Use a self-contained breathing apparatus. Ventilate area. Monitor the surrounding area for Voygen level Section 7: HANDLING AND STORAGE Isolate and threating apparatus. Ventilate area. Monitor the surrounding area for Voygen level Storage requirements: Use atorage containers inplication breating apparatus. Ventilate area. Novid on passurized system. If there is a lesk, close the upstream value, blow down the system by venting to a safe place, threage the upstream value and or surrounding area for Oxygen level Storage requirements: Use storage containers inplication surrounding area for Oxygen level Storage requirements: Use storage containers inplication surrounding area for Oxygen level Use adequate ventilation. Neaver work on a pressurized system. If there is a lesk, close the upstream value, blow down the system by venting to a safe place, threage the leak is the upstream value, blow down the system by venting to a safe place, threage the upstream value, blow down the system by venting to a safe place, threage the leak is the upstream value, blow down the system by venting to a safe place, threage the leak is place, threage the upstream value, blow down the system by venting to a safe place, threage the leak is place, threage the upstream value, blow down the system by venting to a safe place, threage the leak is place, threage the leak is the u	Flammability:	Oxidizer.
Special procedures:       Self-contained reating apparatus required. Frieflighters should wear the usual protective gear. Descennel should be evacuated if measary tuppind area. Remove containers from fire area if without tak.         Auto-ignition temperature:       Not applicable.         Flash point (*C), method       Not applicable.         Lower flammability limit (% vol):       Not applicable.         Upper flammability limit (% vol):       Not applicable.         Explosion Data       Avoid impact against container.         Sensitivity to mechanical impact       Avoid impact against container.         Closed containes may rupture or explode due to pressure build-up when exposed to extreme heat. - Cylinders are equipped with temperature and pressure relief devices but may still rupture under free conditions.         Stop leak without risk.       Wear gloves and gogles Use a self-contained breathing apparatus.         Ventilate area. Monitor the surrounding area for Oxygen level       Stop leak without risk.         Ventilate area. Monitor the surrounding area for Oxygen level       Use adequate ventilation. Never work on a pressurized system. If there is a leak, close the upstream valve, blow down the system by venting to a safe place, th report the leak.         Storage requirements:       Use atoge containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen, Protect lyinders against physical damage. Stor in cool, chy well-ventilated Gaseous Oxygen, Protect clyinders against physical damage. Stor in cool, chy well-ventilated Gaseous Oxygen, Protect clyinders agai	Conditions of flammability:	
Firefighters should wear the usual protective gear.         Cool fire exposed containers with water spray.         Personnel should be evacuated, if necessary, to uppoind area.         Remove containers from fire area if without risk.         Auto-ignition temperature       Not applicable.         Flash point (*C), method.       Not applicable.         Lower flammability limit (\$v vol)       Not applicable.         Upper flammability limit (\$v vol)       Not applicable.         Sensitivity to mechanical impact       Avoid impact against container.         Explosion Data       Colliders are equipped with temperature and pressure build-up when exposed to extreme heat.         Cylinders are equipped with temperature and pressure relief devices but may still rupture under fire conditions.         Storige F : ACCIDENTAL RELEASE MEASURES         Leak/Spill:       Execute al non-essential personnel.         Stop leak without risk.       Wear glowes and googles Use a self-contained breathing apparatus.         Ventilate area. Monitor the surrounding area for Oxygen level         Storage requirement:       Use a stop acquate ventilation. Avoid inhalation. Never work on a pressurized system. If there is a leak, close the upstream valve, blow down the system by venting to a safe place, the repart the leak.         Storage requirement:       Use atorage containers. piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Use d	Extinguishing media:	Use appropriate extinguishing media for surrounding fire.
Flash point (*C), method:       Not applicable.         Lower flammability limit (* voi):       Not applicable.         Upper flammability limit (* voi):       Not applicable.         Explosion Data       Avoid impact against container.         Sensitivity to mechanical impact:       Avoid impact against container.         Explosive power:       Closed containers may rupture or explode due to pressure build-up when exposed to extreme free conditions.         Section 6 : ACCIDENTAL RELEASE MEASURES         Leak/Spill:       Evacuate all non-essential personnel.         Stop leak without risk.       Were gloves and gogies         Use a self-contained breathing apparatus.       Ventilate area. Monitor the surrounding area for Oxygen level         Section 7 : HANDLING AND STORAGE       Leak/Spill:         tandling procedures and equipment:       Protect system components against physical damage. Use adequate ventilation. Avoid inhalation. Never work on a pressure system. If there is a leak, close the upstream valve, blow down the system by venting to a safe place, th repart the leak.         Storage requirement:       Es orage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Use dosignet worth allow area where cylinders against physical damage. Use dosignet worth allow area where cylinders against physical damage.         Use designated CGA fittings and other support equipment. Do not use adapters. Do not drop cylinders or permit them to stikke each other. S	Special procedures:	Firefighters should wear the usual protective gear. Cool fire exposed containers with water spray. Personnel should be evacuated, if necessary, to upwind area.
Lower flammability limit (% vol):       Not applicable.         Uppor flammability limit (% vol):       Not applicable.         Explosion Data       Avoid impact against container.         Sensitivity to meaning the explosion of the explosion o	Auto-ignition temperature:	Not applicable.
limit (% vo):       Not applicable.         Upper flammability limit (% vo):       Not applicable.         Explosion Data       Avoid impact against container.         Explosive power:       Closed containers may rupture or explode due to pressure build-up when exposed to extreme heat.         Cylinders are equipped with temperature and pressure relief devices but may still rupture under fire conditions.         Section 6 : ACCIDENTAL RELEASE MEASURES         Leak/Spill:       Evacuate all non-essential personnel. Stop leak without risk. Wear gloves and goggles Use a self-contained breatting apparatus. Ventilate area. Monitor the surrounding area for Oxygen level         Section 7 : HANDLING AND STORAGE         Handling procedures and equipment:       Use adequate ventilation. Never work on a pressurized system. If there is a leak, close the upstream valve, blow down the system by venting to a safe place, th repair the leak.         Storage requirements:       Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseoux yrom fram against physical damage. Use storage or grave and rom fram against physical damage. Use storage requirements:         Use storage containers. piping, valves and fittings designed for storage and distribution of Gaseoux yrom fram against physical damage. Store in cool, yw.ell-ventilated, fireprof area, avery from frammability. Do not store neer devators, corritors or loading docks. Do not allow area where cylinders against physical damage. Store neer devators, corritors or loading docks. Do not allow area where cylinders are stored to exceed 52°C (125°F).         Move cylind	Flash point (°C), method:	Not applicable.
Imit (% vol):       Not applicable.         Explosion Data       Avoid impact against container.         Explosive power:       Closed containers may rupture or explode due to pressure build-up when exposed to extreme heat.         Cylinders are equipped with temperature and pressure relief devices but may still rupture under fire conditions.         Section 6 : ACCIDENTAL RELEASE MEASURES         Leak/Split:       Evacuate all non-essential personnel.         Stop leak without risk.       Wear gloves and goggles         Use a self-contained breathing apparatus.       Ventilate area. Monitor the surrounding area for Oxygen level         Section 7 : HANDLING AND STORAGE       Leak/Split:         tandling procedures and equipment:       Protect system components against physical damage.         Use adequate ventilation.       Avoid inhalation.         Never work on a pressurized system.       If there is a leak. Close the upstream valve, blow down the system by venting to a safe place, threpair the leak.         Storage requirements:       Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool. dry, well-ventilated, fireproof area, away from Itamable materials and corrosive atmospheres. Store away from here and lightion sources and out of direct sunlight. Do not store near elevators, cordinors or loading docks. Do not allow area where cylinders are stored to exceed 52°C (125°F).         Move cylinders with a suitable hand-truck. Do not dreag sli	Lower flammability limit (% vol):	Not applicable.
Sensitivity to mechanical impact:       Avoid impact against container.         Explosive power:       Closed containers may rupture or explode due to pressure build-up when exposed to extreme heat.         Cylinders are equipped with temperature and pressure relief devices but may still rupture under fire conditions.         Section 6 : ACCIDENTAL RELEASE MEASURES         Leak/Spill:       Evacuate all non-essential personnel.         Stop leak without risk.       Wear gloves and goggles         Use a self-contained breathing apparatus.       Ventilate area. Monitor the surrounding area for Oxygen level         Section 7 : HANDLING AND STORAGE       Handling procedures and equipment:         Avoid inhalation.       Never work on a pressurized system.         If there is a leak, close the upstream valve, blow down the system by venting to a safe place, the repair the leak.         Storage requirements:       Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool, dry, well-ventilated, frieproof area, away from fiae materials and corrosive atmospheres. Store away from hear and ignition sources and out of direct sunlight. Do not store near elevators, corridors or loading docks. Do not allow area where cylinders are stored to exceed 52°C (125°F).         Move cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not heat cylinders or permit them to strike each other. Secure cylinders firmly. Leave the valve protection cap in-place (where provided) until cylinder is placed into service. <td></td> <td></td>		
Explosive power:       Closed containers may rupture or explode due to pressure build-up when exposed to extreme heat.         Cylinders are equipped with temperature and pressure relief devices but may still rupture under fire conditions.         Section 6 : ACCIDENTAL RELEASE MEASURES         Leak/Spill:       Evacuate all non-essential personnel.         Stop leak without risk.       Wear gloves and goggles         Use a self-contained breathing apparatus.       Ventilate area. Monitor the surrounding area for Oxygen level         Section 7 : HANDLING AND STORAGE       Section 7 : HANDLING AND STORAGE         tandling procedures and equipment:       Protect system components against physical damage.         Use adequate ventilation.       Avoid inhalation.         Avoid inhalation.       Never work on a pressurized system.         If there is a leak, close the upstream valve, blow down the system by venting to a safe place, the repair the leak.         Storage requirements:       Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool, dry, well-wentilated, fireproof area, away from flammable materials and corrosive atmospheres. Store away from hear and ignition sources and out of direct sunlight. Do not store near elevators, corridors or loading docks. Do not allow area where cylinders are stored to exceed 52°C (125°F).         Move cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not drop cylinders or permit them to stirke each other. Secure cylinders f	Explosion Data	
heat.         Cylinders are equipped with temperature and pressure relief devices but may still rupture under fire conditions.         Section 6 : ACCIDENTAL RELEASE MEASURES         Leak/Spill:       Evacuate all non-essential personnel.         Stop leak without risk.       Wear gloves and goggles         Use a self-contained breathing apparatus.       Ventilate area. Monitor the surrounding area for Oxygen level         Section 7 : HANDLING AND STORAGE         tandling procedures and equipment:       Protect system components against physical damage.         Use adequate ventilation.       Avoid inhalation.         Never work on a pressurized system.       If there is a leak, close the upstream valve, blow down the system by venting to a safe place, the repair the leak.         Storage requirements:       Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool, dry, well-ventilated, fireproof area, away from filemable materials and corrosive atmospheres. Store away from hearials and corrosive atmospheres. Do not drop cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not drop cylinders or permit them to strike each other. Secure cylinders firmly, Leave the valve protection cap in-place (where provided) until cylinder is placed into service and after it is taken out of service.         Use designated CGA fittings and other support equipment. Do not		
Leak/Spill:       Evacuate all non-essential personnel. Stop leak without risk. Wear gloves and goggles Use a self-contained breathing apparatus.         Ventilate area.       Monitor the surrounding area for Oxygen level         Section 7 : HANDLING AND STORAGE         Handling procedures and equipment:       Protect system components against physical damage. Use adequate ventilation. Avoid inhalation. Never work on a pressurized system. If there is a leak, close the upstream valve, blow down the system by venting to a safe place, the repair the leak.         Storage requirements:       Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool, dry, well-ventilated, fireproof area, away from flammable materials and corrosive atmospheres. Store away from hea and ignition sources and out of direct sunlight. Do not store near elevators, corridors or loading docks. Do not allow area where cylinders are stored to exceed 52°C (125°F).         Move cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not drop cylinders or permit them to strike each other. Secure cylinders firmly. Leave the valve protection cap in-place (where provided) until cylinder is placed into service and after it is taken out of service.         Use designated CGA fittings and other support equipment. Do not use adapters. Do not heat cylinder by any means to increase the discharge rate of the product from the cylinder. Use chec valve or trap in discharge line to prevent hazardous backflow into the cylinder. Do not use oils o grease on gas-handling fittings or equipment.	Explosive power:	heat. Cylinders are equipped with temperature and pressure relief devices but may still rupture under
Stop leak without risk.         Wear gloves and goggles         Use a self-contained breathing apparatus.         Ventilate area. Monitor the surrounding area for Oxygen level         Section 7 : HANDLING AND STORAGE         Handling procedures and equipment:         Protect system components against physical damage.         Use adequate ventilation.         Avoid inhalation.         Never work on a pressurized system.         If there is a leak, close the upstream valve, blow down the system by venting to a safe place, the repair the leak.         Storage requirements:       Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool, dry, well-ventilated, fireproof area, away from flammable materials and corrosive atmospheres. Store away from hear and ignition sources and out of direct sunlight. Do not store near elevators, corridors or loading docks. Do not allow area where cylinders are stored to exceed 52°C (125°F).         Move cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not drop cylinders or permit them to strike each other. Secure cylinders. Do not drop cylinders or permit them to strike each other. Secure cylinders. Do not use of service.         Use designated CGA fittings and other support equipment. Do not use adapters. Do not use oils o grease on gas-handling fittings or equipment.         After use, close main cylinder valve. Replace valve protection cap (where provided). Mark empti		Section 6 : ACCIDENTAL RELEASE MEASURES
<ul> <li>Handling procedures and equipment: Protect system components against physical damage. Use adequate ventilation. Avoid inhalation. Never work on a pressurized system. If there is a leak, close the upstream valve, blow down the system by venting to a safe place, the repair the leak.</li> <li>Storage requirements: Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool, dry, well-ventilated, frieproof area, away from flammable materials and corrosive atmospheres. Store away from here and ignition sources and out of direct sunlight. Do not store near elevators, corridors or loading docks. Do not allow area where cylinders are stored to exceed 52°C (125°F).</li> <li>Move cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not drop cylinders or permit them to strike each other. Secure cylinders firmly. Leave the valve protection cap in-place (where provided) until cylinder is placed into service and after it is taken out of service.</li> <li>Use designated CGA fittings and other support equipment. Do not use adapters. Do not heat cylinder by any means to increase the discharge rate of the product from the cylinder. Use other valve or trap in discharge line to prevent hazardous backflow into the cylinder. Do not use oils o grease on gas-handling fittings or equipment.</li> </ul>	Leak/Spill:	Stop leak without risk. Wear gloves and goggles Use a self-contained breathing apparatus.
Use adequate ventilation. Avoid inhalation. Never work on a pressurized system. If there is a leak, close the upstream valve, blow down the system by venting to a safe place, the repair the leak. Storage requirements: Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool, dry, well-ventilated, fireproof area, away from flammable materials and corrosive atmospheres. Store away from hea and ignition sources and out of direct sunlight. Do not store near elevators, corridors or loading docks. Do not allow area where cylinders are stored to exceed 52°C (125°F). Move cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not drop cylinders or permit them to strike each other. Secure cylinders firmly. Leave the valve protection cap in-place (where provided) until cylinder is placed into service and after it is taken out of service. Use designated CGA fittings and other support equipment. Do not use adapters. Do not heat cylinder by any means to increase the discharge rate of the product from the cylinder. Use chec valve or trap in discharge line to prevent hazardous backflow into the cylinder. Do not use oils o grease on gas-handling fittings or equipment. After use, close main cylinder valve. Replace valve protection cap (where provided). Mark empt		Section 7 : HANDLING AND STORAGE
docks. Do not allow area where cylinders are stored to exceed 52°C (125°F). Move cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not drop cylinders or permit them to strike each other. Secure cylinders firmly. Leave the valve protection cap in-place (where provided) until cylinder is placed into service and after it is taken out of service. Use designated CGA fittings and other support equipment. Do not use adapters. Do not heat cylinder by any means to increase the discharge rate of the product from the cylinder. Use chec valve or trap in discharge line to prevent hazardous backflow into the cylinder. Do not use oils o grease on gas-handling fittings or equipment.		Use adequate ventilation. Avoid inhalation. Never work on a pressurized system. If there is a leak, close the upstream valve, blow down the system by venting to a safe place, the repair the leak. Use storage containers, piping, valves and fittings designed for storage and distribution of Gaseous Oxygen. Protect cylinders against physical damage. Store in cool, dry, well-ventilated, fireproof area, away from flammable materials and corrosive atmospheres. Store away from hea
cylinder by any means to increase the discharge rate of the product from the cylinder. Use chec valve or trap in discharge line to prevent hazardous backflow into the cylinder. Do not use oils o grease on gas-handling fittings or equipment. After use, close main cylinder valve. Replace valve protection cap (where provided). Mark empt		docks. Do not allow area where cylinders are stored to exceed 52°C (125°F). Move cylinders with a suitable hand-truck. Do not drag, slide or roll cylinders. Do not drop cylinders or permit them to strike each other. Secure cylinders firmly. Leave the valve protection cap in-place (where provided) until cylinder is placed into service and after it is taken out of
		cylinder by any means to increase the discharge rate of the product from the cylinder. Use chec valve or trap in discharge line to prevent hazardous backflow into the cylinder. Do not use oils o
		After use, close main cylinder valve. Replace valve protection cap (where provided). Mark empt

## Precautionary Measures



Respiratory/Type:	NIOSH/MSHA approved respirator.
Eye/Type:	As per local regulations.
Footwear/Type:	Safety boots per local regulations.
Clothing/Type:	Wear adequate protective clothes.
Other/Type:	Eye wash facility should be in close proximity. Emergency shower should be in close proximity.
Ventilation requirements:	Mechanical ventilation is satisfactory. Ensure oxygen concentration remains above 19.5% and Carbon Dioxide concentration does not exceed 5000 ppm, Local exhaust at points of emission preferred.
Exposure limit of material	Not available.

## Section 9 : PHYSICAL AND CHEMICAL PROPERTIES

Physical state:	Gas
Appearance & odor:	Colorless, odorless gas.
Odor threshold (PPM):	Odorless.
Vapor pressure :	Gas@ 70°F (21°C)
Vapor sp. gravity (air=1):	1.11 @ 70°F (21°C)
Volatiles (% by volume)	100%
Boiling point :	-183°C (760 mmHg) -297.4°F
Freezing point :	-218.8°C -361.8°F
Solubility in water (%):	Slight.

#### Section 10 : STABILITY AND REACTIVITY

Chemical stability:	Product is stable.
Conditions of reactivity:	Heat
Hazardous polymerization:	Will not occur.
Incompatible substances:	Combustible materials. Oils or grease. Flammable materials.
ordous decomposition productor	Nono

Hazardous decomposition products: None.

## Section 11 : TOXICOLOGICAL INFORMATION

LD50 of product, species & route: Not available.

LC50 of product, species & route: Not available.

#### Section 13 : DISPOSAL CONSIDERATIONS

Waste disposal: Gas will dissipate in air. Cylinders should be returned in the original shipping container, properly labeled, with any valve outlet plugs or caps secured and valve protection cap in place.

## Section 14 : TRANSPORT INFORMATION

## DOT/ TDG classification:

For cylinder shipments: Oxygen, compressed UN1072 Class 2.2 (Non-Flammable Gas) with subsidiary risk 5.1 (Oxidizer)



Emergency Response Guidebook 0244-330-594

## Section 16 : OTHER INFORMATION

#### Definitions and other useful data:

CAS #: The Chemical Abstract Service Number which uniquely identifies each constituent.

ACGIH - American Conference of Governmental Industrial Hygienists, a professional association which establishes exposure limits.

**TLV** - Threshold Limit Value - an airborne concentration of a substance which represents conditions under which it is generally believed that nearly all workers may be repeatedly exposed without adverse effect.

OSHA - U.S. Occupational Safety and Health Administration.

PEL - Permissible Exposure Limit - The same value as a TLV, except it is enforceable by OSHA.

**IDLH** - Immediately Dangerous to Life and Health - A concentration from which one can escape within 30-minutes without suffering permanent injury.

## NATIONAL FIRE PROTECTION ASSOCIATION:

### Health Hazard Rating Scale (Blue):

- 0 (material that on exposure under fire conditions would offer no hazard beyond that of ordinary combustible materials);
- 1 (materialsthat on exposure under fire conditions could cause irritation or minor residual injury);
- 2 (materials that on intense or continued exposure under fire conditions could cause temporary incapacitation or possible residual injury);
- 3 (materials that can on short exposure could cause serious temporary or residual injury);
- 4 (materials that under very short exposure could cause death or major residual injury). Flammability Hazard Rating Scale (Red):
- **0** (minimal hazard);
- 1 (materials that require substantial pre-heating before burning);
- 2 (combustible liquid or solids; liquids with a flash point of 38-93°C [100-200°F]);
- 3 (Class IB and IC flammable liquids with flash points below 38°C [100°F]);
- 4 (Class IA flammable liquids with flash points below 23°C [73°F] and boiling points below 38°C [100°F].

## Reactivity Hazard Rating Scale(Yellow):

- 0 (normally stable);
- 1 (material that can become unstable at elevated temperatures or which can react slightly with water);
- 2 (materials that are unstable but do not detonate or which can react violently with water);
- 3 (materials that can detonate when initiated or which can react explosively with water);
- 4 (materials that can detonate at normal temperatures or pressures).

## TOXICOLOGICAL INFORMATION:

Possible health hazards as derived from human data, animal studies, or from the results of studies with similar compounds are presented. Definitions of some terms:

LD50 -Lethal Dose (solids & liquids) which kills 50% of the exposed animals;

LC50 - Lethal Concentration (gases) which kills 50% of the exposed animals; ppm concentration expressed in parts of material per million parts of air or water; mg/m3 concentration expressed in weight of substance per volume of air; mg/kg quantity of material, by weight.

#### **REGULATORY INFORMATION:**

EPA is the U.S. Environmental Protection Agency.

WHMIS is the Canadian Workplace Hazardous Materials Information System.

**DOT** and **TC** are the U.S. Department of Transportation and the Transport Canada, respectively, which assign DOT and **TDG** (Transportation of Dangerous Goods) identification numbers, hazard classifications, and proper shipping name and shipping label information. This material is hazardous as defined by 49 CFR 172.101 of the US Department of Transportation and Dangerous Goods as defined by Transport Canada Transportation of Dangerous Goods Regulations.

## **USE OF THIS INFORMATION:**

Takoradi Gas Ltd offers this information to customers, employees, contractors, and the general public to promote the safe use of this product through awareness of product hazards and safety information. Customers and others who use or transport or sell this product to others should: 1) Disseminate this information internally to all workplace areas, employees, agents and contractors likely to encounter this product; 2) Provide supplemental hazards awareness, safety information, operation and maintenance procedures to the workplace areas and employees, agents and contractors likely to encounter this product; 3) Furnish this information to all their customers who purchase this product; and 4) Ask each purchaser or user of the product to notify its employees and customers of the product hazards and safety information.

## DISCLAIMER OF EXPRESSED AND IMPLIED WARRANTIES:

Takoradi Gas Ltd. has taken reasonable care in preparing this document, however, since the use of this information and the conditions of use of the product are not within the control of Takoradi Gas Ltd., it is the user's obligation to determine the conditions of safe use of this product. The information in this document is offered with no warranties or representations as to accuracy or completeness and it is the responsibility of each individual to determine the suitability of the information for their particular purpose(s).

Updated: 26 March 2024